
# **SCHONBEK**<sup>®</sup>




HIS DESIGN IS THE PROPRIETARY TRADE DRESS/TRADEMARK OF SWAROVSKI LIGHTING, LTD.

HANGING WEIGHT: 19 lbs.

IIV Wi
ou
ee
ee
e

e crystal package label. e crystal package label.



Use a soft, lint - free cloth to clean the metal frame.

### **UNDER NO CIRCUMSTANCES** SHOULD METAL POLISHES, CLEANERS, **ABRASIVES OR AEROSOL SPRAYS BE USED.**

While the latest finishing techniques have been used on the metal frame, such finish cannot be unconditionally guaranteed. The main cause of deterioration, apart from certain atmospheric conditions, is improper cleaning.

To clean the crystals, polish with a damp chamois.

You are cleaning delicate jewelry... Take the greatest care.


Do not clean crystals in a dishwasher. The finish of the metal clips and hangers will be ruined and the crystals may be damaged.


5868-\_\_\_S

5868-\_\_\_S

## **MAINTENANCE:**

### **IMPORTANT:**





5868-\_\_\_S

PAGE 3

**6** Screw finial assembly onto bottom of chandelier. Hook Crystal Chain "E" (large crystal towards top) into the ring 2. Allow bottom of chain to hang freely.

**7** Hook Crystal "F" into the washer on the finial assembly. See diagram 1 for detailed instructions.


 ${\bf 8}$  Hook the bottom of Chains "E" into the washer. Close bottom hook after inserting into washer.


**9** Hook Crystal "G" into the back slot of the "Y" bracket of ring 1. See diagram 2 for detailed instructions.

**10** Hook Crystal "B" into the "plain" bracket of ring 1. See diagram 3 on page 6.

**11** Hook small Crystal "C" into every second "Y" bracket of ring 1. See diagram 4 on page 6.

**12** Hook large Crystal "D" into the remaining "Y" brackets of ring 1. See diagram 4 on page 6.





5868-\_\_\_S

PAGE 4

5868-\_\_\_S

PAGE 5