#### **CHANDELIER 3587-**

### **MAINTENANCE:**

Use a soft, lint - free cloth to clean the metal frame.

### **UNDER NO CIRCUMSTANCES** SHOULD METAL POLISHES, CLEANERS, **ABRASIVES OR AEROSOL SPRAYS BE USED.**

While the latest finishing techniques have been used on the metal frame, such finish cannot be unconditionally guaranteed. The main cause of deterioration, apart from certain atmospheric conditions, is improper cleaning.


To clean the crystals, polish with a damp chamois.

You are cleaning delicate jewelry... Take the greatest care.

#### **IMPORTANT:**

Do not clean crystals in a dishwasher. The finish of the metal clips and hangers will be ruined and the crystals may be damaged.

# **SCHONBEK**<sup>®</sup>




TRADE DRESS/TRADEMARK OF SCHONBEK WORLDWIDE LIGHTING INC.


## **SCHONBEK**<sup>®</sup>

#### Follow steps in exact order Save this trim diagram for future reference

			son who d llowing i	
	PACKER			' S
	ORDER	#		S
l		#		2

IMPORTANT pens carton should record the formation for future service. Four-digit number on outside of carton. See crystal package label. See crystal package label.





**〔17**〕


3587-\_\_\_-

3587-\_\_\_-\_\_\_\_


















(N10191\*\*) 3" 76mm



(N10276) . 3-1/2" 89mm

L






diagram.

3587-\_\_\_-

PAGE 6

3587-\_\_\_-\_\_

### For easy removal of crystal from bubble pack, please cut along pouches on the inside of the seam. Gently remove crystal from the side of the pouch.

## NOTE: Work on one crystal set at a time. Follow the black line from top to bottom according to the numbered steps on the trim

